



# Harmful Algal Bloom (HAB) Satellite Imagery NOAA – NOS, Copernicus Sentinel-3a

This data product is experimental. Cyanobacteria detections should be confirmed and may not indicate presence of cyanotoxins.

Learn more about HABs at [ohioalgaefinfo.com](http://ohioalgaefinfo.com)

Find beach advisories and sampling data at

<http://publicapps.odh.ohio.gov/beachguardpublic>

## Chippewa Lake MEDINA COUNTY

Satellite Image Taken: 06/21/2022  
V2 PROCESSING & COLOR RAMP

Public Water System Intake

ODNR Sample Sites



[EPAHABmailbox@epa.ohio.gov](mailto:EPAHABmailbox@epa.ohio.gov)

Report Date: 06/22/2022