



Harmful Algal Bloom (HAB) Satellite Imagery NOAA – NOS, Copernicus Sentinel-3ab

This data product is experimental. Cyanobacteria detections should be confirmed and may not indicate presence of cyanotoxins.

Learn more about HABs at ohioalgaefinfo.com

Find beach advisories and sampling data at

<http://publicapps.odh.ohio.gov/beachguardpublic>

Chippewa Lake MEDINA COUNTY

Satellite Image Taken: 08/12/2022
V2 PROCESSING & COLOR RAMP

Public Water System Intake

ODNR Sample Sites



EPAHABmailbox@epa.ohio.gov

Report Date: 08/16/2022